

Schnellinstallationshandbuch

Guía de instalación rápida

Rövid üzembe helyezési útmutató



ES

PT

FI

Avaa kytkentärasia.

Löysää kulmissa olevat ruuvit (yht. 4)
ruuviavaimella ja poista suoja Levy.


RU

TR


Bağlantı kutusunu açın

Her bir köşedeki 4 vidayı tornavidayla
gevşetin ve kapak plakasını çıkartın.
Vidalar kapağa sabitlenmiştir, bu nedenle
dışarı çıkamazlar.

AR







ES

**Encienda la alimentación de la red
(caja de fusibles)**

PT

**Desligar a alimentação eléctrica
(contador eléctrico)**

FI

**Kytke pääkatkaisimen virta pois päältä
(sähkökaappi)**


RU


**Отключите питание в сети электропитания
(шкафу электросчетчика)**

TR

Ana şalteri (elektrik sayacı kutusu) kapatın

AR





Position and secure receiver

The receiver can only be positioned in 1 way. Once in position, secure the receiver with screws.

ES

PT

FI

Asenna vastaanotin ja kiinnitä se paikoilleen.

Vastaanotin voidaan d2.2vbsta (pai(oillee .))JcTc[2vbatinyhdelltäta)8[2vballa. Kv
pai(oildaa,a k)-7(tir)-4(sitä seruu v)10eoildn.
O

RU

е приемник винвiny юjaci(bindel r)9bdec9bdpkt
pkt


. Unna ven u posici(Bi,n d2gur)

TR

Akımyı yerleřtirin ve sabitleyin

Akımyı sabitleyin ve yonlu olarak yerleřtirilebilir.
Alınan verilerden sonra vidalarla
sabitleyin.

AR



Tighten cable glands

Tighten the cable glands by turning clockwise to protect the inside from dust and moist. Use 7-12 mm diameter cable for an optimal seal. Other cable sizes can negatively affect the waterproofness of the junction box.





ES

PT

FI

Asenna kytkentärasia

Kiinnitä kytkentärasia seinään tai muulle pinnalle vak

RU


Закрепите соединительную коробку.


TR


Bağlantı kutusunu takın

Ekstra stabilite için bağlantı kutusunu bir duvara veya başkeye sabitleyin.

AR









EC DECLARATION OF CONFORMITY (DoC)